

Simon Greenwood

Scale Model Railways

7mm J.S.Beeson LMS Stanier 2-6-4 Tank restoration by Simon Greenwood



- Service motor & gearbox
- Fabricate: front RH steps, rear buffer beam, smoke box number plate, missing lamp iron, frame stretcher, new pickups.
- Repair of damage to rear of loco frame in order to mount new frame stretcher

- Remove old pickups and non-original mounting block, and affix new pickups with new wiring to motor
- Polish all motion parts & wheels, fit new handrails all round
- Paint & Line in LMS Black, lined Red Livery

