

# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

## O Gauge Bassett Lowke Live Steam 2-6-0 Stanier Mogul No 2945 Tender Locomotive – Before Restoration



### Repair/Fabrication of missing parts:

- Improve ripples in Cab Plate work, Fabricate and Fit new Engine to Tender Coupling
- Fabricate and Fit Filler Plug for Spirit Reservoir, check cylinders are steam tight. Check Safety valve, set for 25 psi
- Supply and fit fibre washers for lubricator tank plugs and safety valve/water filler
- Re-solder hand rail knob to re-attach, fix loose Smoke Box Hand rails and Cab Hand rails

### Improvement of existing damaged paint work:

- Sensitive touch up the more serious damaged and missing paint work
- Add ageing to blend with existing paintwork



# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

O Gauge Bassett Lowke Live Steam 2-6-0 Stanier Mogul No 2945 Tender Locomotive – After Restoration by Simon Greenwood

